Serial-Killer

Security Analysis of Industrial Serial Device Servers



Dr. Florian Adamsky October 18, 2018

University of Luxembourg, SECAN-Lab



Introduction

Related Work

Found Vulnerabilities

1

Conclusion

Introduction

16:00 at 23.12.2015 in Western Ukraine

Prykarpattyaoblenergo



Figure 1: Source: derstandard.at

Press Release (Google Translate)



Results of the work

Investments

Social Responsibility

Awards

Currently specialists of PJSC "Prykarpattyaoblenergo" are looking for reasons and find out the scale of the accident.

We will provide more detailed information as we receive it.

Please refrain from making phone calls to the Call Center, since the unknown cause of the accident is unknown, dispatchers do not have information on the terms of the renewal of the electricity supply! Thank you for understanding!

5

my.oe.if.ua



Analysis of the Cyber Attack on the Ukrainian Power Grid

Defense Use Case

March 18, 2016

1325 G Street NW Suite 600 Washington, DC 20005

Summary what happend

- Outage were due to an attack against the SCADA infrastructure
- Approximately 225.000 customers were without power in three different distribution-level
- These attacks in Ukraine are the first publicly acknowledged incidents to result in power outages

Who was it?

Geopolitical Questions

I don't know



Background on the Attacks

- Attacker send spear phishing emails
- Variants of the BlackEnergy 3 malware
- Manipulation of Microsoft Office documents which contain malware
- Telephone DDoS Attack

Attacks against substations

Adversaries attacked field devices at substations: "write custom malicious firmware, and render the devices, such as serial-to-ethernet convertors, inoperable and unrecoverable."

• Investigate how big the security threat is regarding these devices

Other use cases (Brewery Tank Monitoring)



Industrial Tank Monitoring

Other use cases (Medical Device Monitoring)



Figure 2: https://www.lantronix.com/products/eds-md/



Figure 3: Overview about a generic serial server containing relevant interfaces.

Related Work

- HD Moore gave a talk at InfoSec Southwest 2013
- Mostly focused on the company Digi
- Found scary stuff directly connected on the Internet

2013: HD Moore

Dry Cleaners

- HD M
- Mostl
- Found

National Dry Cleaner Chains

- Full access to PoS systems
 - No authentication



				Store :	Sales S	ummary		Discs/	Cash/
	Category	#Tiks	Total Amt	Tax1/2	#Pcs	Upchrgs	Tik Chg	Coupons	A/R Chg
	LEATHER		456.58	.00 36.52				. 00 . 00	440.18 52.92
	WEDDING			.00 .00				. 00 . 00	.00 .00
	FUTURE			.00 .00				. 00 . 00	. 00 . 00
	7							CLEANERS	390
RAPID	Store Sales Summary							Discs/	Cash/

2013: HD Moore

Traffic Light Control

- HD M EDI Traffic Signal Monitors
- Mostl
- Found

- > Based on Digi development kits, exposes ADDP
 - Default password is "dbps" as a result
 - ~40 or so identified in the Internet Census 2012 data



- Thomas Roth gave a talk last year on 34c3 with the title "SCADA Gateway to (s)hell "
- Focused on:
 - Advantech EKI-1522
 - Moxa W2150A
 - Lantronix EDS2100

Found Vulnerabilities

Alternative Title



Moxa NPort 5110/5130



Internet-wide Scans (ZMap)

- Daily scans with ZMap on https://censys.io
- Analysed telnet scan from 2018-08-21
- 1877 Moxa NPort devices directly connected to the Internet
- 1150 Moxa NPort 5110/5130



















SYN-Flooding Attack (CVE-2017-14028)


SYN-Flooding Attack (CVE-2017-14028)



SYN-Flooding Attack (CVE-2017-14028)



SYN-Flooding Attack (CVE-2017-14028)



```
Welcome to Scapy (unknown.version)
$ sr1(IP(dst="192.168.127.254")/ICMP())
Begin emission:
.....Finished to send 1 packets.
```

```
Welcome to Scapy (unknown.version)
$ sr1(IP(dst="192.168.127.254")/ICMP())
Begin emission:
.....Finished to send 1 packets.
```

```
Received 7 packets, got 1 answers, remaining 0 packets
<IP version=4L ihl=5L tos=0x0 len=28 id=39957 flags=
frag=0L ttl=255 proto=icmp chksum=0x9f7a src=192.168.
127.254 dst=192.168.127.1 options=[] <ICMP type=echo
-reply code=0 chksum=0xffff id=0x0 seq=0x0 |<Padding
load='\xf8\x12\xe0\xbfP\x11\x10\x00\xc5\xdf\x00\x00HTTP/1' |>>>
```

Moxa NPort 5110: Etherleaking (CVE-2017-16715)

- Vulnerable to Etherleaking
 - Expose portion of the kernel memory
- \cdot According to RFC 894 an Etherframe \geq 46 Bytes
- What if a packet is smaller?

RFC 894:

IP packet "should be padded (with octet of zero) to meet the Ethernet minimum frame size"

Problem of Etherleaking (Example)

```
void xmit_frame(char *frame_buf, int frame_len) {
    int length;
```

```
if (frame_len < MIN_FRAME_SZ)
    length = MIN_FRAME_SZ;</pre>
```

else

```
length = frame_len;
```

```
copy_to_tx_buf(frame_buf, length);
```

return;

Problem of Etherleaking (Example)

```
void xmit_frame(char *frame_buf, int frame_len) {
    int length;
```

if (frame_len < MIN_FRAME_SZ)</pre>

length = MIN_FRAME_SZ;

else

```
length = frame_len;
```

```
copy_to_tx_buf(frame_buf, length);
```

return;

Problem of Etherleaking (Example)

```
void xmit_frame(char *frame_buf, int frame_len) {
    int length;
```

```
if (frame_len < MIN_FRAME_SZ)
    length = MIN_FRAME_SZ;
    using uninitialized
    memory as padding.
else</pre>
```

```
length = frame_len;
```

```
copy_to_tx_buf(frame_buf, length);
```

return;

```
void xmit_frame(char *frame_buf, int frame_len) {
    int length;
```

```
if (frame_len < MIN_FRAME_SZ) {
    length = MIN_FRAME_SZ;
    memset(frame_buf + frame_len, 0, length - frame_len);
} else
    length = frame_len;</pre>
```

```
copy_to_tx_buf(frame_buf, length);
```

return;

RFC 1948

The initial sequence numbers are intended to be more or less random. More precisely, RFC 793 specifies that the 32-bit counter be incremented by 1 in the low-order position about every 4 microseconds.

- TCP Initial Sequence Number (ISN) should be competently random
- If not \rightarrow Attacker can predict the next SN and inject arbitrary packets into an established TCP connection
- \cdot We found out that Moxa Embedded uses the uptime of the device as ISN

<pre>\$ sudo python2</pre>	.7 tcp-isn.py
ISN Diff	erence
1903050 +9	5
1903125 +7	5
1903220 +9	5
1903310 +9	0
[]	

 An attacker can get the uptime of the device via SNMP by requesting the OID sysUpTimeInstance

Moxa NPort 5110: Connection Blocking

- NPort 5110 uses TCP port 950/966 for the serial connection
 - TCP Port 966: signaling
 - TCP Port 950: data
- Both port accept connections without authentication
- $\cdot\,$ Only 1 connection is allowed \rightarrow all other connections will be blocked
- \cdot An attacker needs to connect to both ports and hold the connection open
 - Legitimate users cannot connect to the device anymore

Moxa NPort 5110: No firmware verification

- If you have access to web GUI you can upload firmware images
- Moxa NPort 5110 does not support firmware verification
- You can upload a malicious firmware and the device will write it to memory
- How did we found out?

Moxa NPort 5110: No firmware verification

- If you have access to web GUI you can upload firmware images
- Moxa NPort 5110 does not support firmware verification
- You can upload a malicious firmware and the device will write it to memory
- How did we found out?
 - We tested it and bricked one device ;-)

Hi-Fly DTU-E100



Hi-Fly DTU-E100

- Sold under different cases
- Support TCP/UDP/HTTP/TLS/Modbus Network Protocols
- Support RS232/RS485/Ethernet Data Interface





Hi-Fly DTU-E100

Available with Wireless LAN

- Sold under different c
- Support TCP/UDP/HTTP/TLS/M Network Protocols
- Support RS232/RS485, Interface



Hi-Fly DTU-E100 Web Interface

			中文 English	
Quick Configure	Ethernet Ports Setting	3		
Application Setting Ethernet Setting	Open or closed modules Ethernet Ports			
HTTPD Client Mode	Ethernet function	Epable		
WEB IO	Set the Ethernet work mode	LAN port V		
Advanced	,	Apply Cancel		
Device Management				

Hi-Fly DTU-E100: Open Wireless LAN

- According to the manual this device should not have a wireless LAN
- According to the web GUI, this device should not have a wireless LAN
- We found out this device has an un-encrypted and open wireless LAN with the essid DTU-H100_24B4
- Can only deactivated via telnet with AT+T commands



Hi-Fly DTU-E100: Connection Blocking

- Similar to Moxa NPort device
- This device allows 32 TCP connection simultaneously
- An attacker just has to start 32 TCP connections on that port to block any legitimate user to reach this device
- This is also possible when password authentication is enabled

Hi-Fly DTU-E100: Flooding Attack

- Default TCP window size is very low
- A couple of larger TCP packets are enough to exhausted the window size and the device cannot receive any packets



Web Interface

Industrial Device Server

MENU

IP Configuration

Serial Device Server

System
- System Information
SNTP
IP Configuration
User Authentication
Port Serial Setting
··· Serial Configuration
Port Profile
Service Mode
Management
- Access IP Control List
SMTP/SNMP Conf.
System Event Conf.
Save/Reboot
Help

IP Configuration	Static V				
IP Address	192.168.10.2				
Netmask	255.255.255.0				
Gateway	192.168.10.1				
DNS Server 1	192.168.10.1				
DNS Server 2					
Auto IP Report					
Auto Report to IP					
Auto Report to TCP Port	0				
Auto Report Interval	0 seconds				
Ethernet Mode					
Ethernet Mode	• Redundant Switch				

XSS (CVE-2018-8869)

Indust	trial Device	Server		
MENU	SNTP Configuration			
Serial Device Server	Name			
System Information				
IP Configuration				
Port Serial Setting			XSS	
Serial Configuration Port Profile				
Service Mode			ОК	
Access IP Control List				
System Event Conf.				
Save/Reboot Help				

\$ binwalk -e IDS-2102_V1.1h.bin

DECIMAL HEXADECIMAL DESCRIPTION

846000x14A78CRC32 polynomial table, little endian1433080x22FCCgzip compressed data, maximum compression11718280x11E174gzip compressed data, has file name: "ramdisk"

Comparision between ser2net

Radare2 Analyse of the Binary

[0x0000a688]> afl~sel_

0x00017240 sym.sel_set_fd_handlers

0x0001728c sym.sel_clear_fd_handlers

0x00017344 sym.sel_set_fd_read_handler

0x0001739c sym.sel_set_fd_write_handler

0x00017400 sym.sel_set_fd_except_handler

Radare2 Analyse of the Binary

[0x0000a688]> afl~sel_

0x00017240 sym.sel_set_fd_handlers

0x0001728c sym.sel_clear_fd_handlers

0x00017344 sym.sel_set_fd_read_handler

0x0001739c sym.sel_set_fd_write_handler

0x00017400 sym.sel_set_fd_except_handler

Ser2net (Open Source)

\$ cat selector.h | grep "^void_sel"
void sel_set_fd_handlers(...)
void sel_clear_fd_handlers(...)
void sel_set_fd_read_handler(...);
void sel_set_fd_write_handler(...);
void sel_set_fd_except_handler(...);

Comparision between ser2net

Radare2 Analyse of the Bi

[0x0000a688]> afl~sel_ 0x00017240 sym.sel_set_fd_ha 0x0001728c sym.sel_clear_fd_ 0x00017344 sym.sel_set_fd_re 0x0001739c sym.sel_set_fd_wr 0x00017400 sym.sel_set_fd_ex

GPL Violation?



າ Source)

h | grep "^void_sel"
_handlers(...)
fd_handlers(...)
_read_handler(...);
_write_handler(...);
_except_handler(...);

1. Run binary with chroot and qemu-arm-static

```
sudo chroot . qemu—arm—static —g 1337 /usr/bin/ser2net —p 600 —c /etc/com2ip.conf
```

1. gdb-multiarch with gef

\$ gdb—multiarch

gdb> set gnutarget elf32—littlearm

gdb> file /mnt/disk/usr/bin/ser2net

gdb> target remote localhost:1337

```
version:
model:DS-12
name:DeviceServer-DEFAULT
serialno:123456789-12-456
password:
network:static:192.168.10.2:255.255.255.0:AAAAAAAAAAAAAAAA:192.168.10.1
snmp:empty:empty:empty:empty:empty:empty
email:::::::
management:web:telnet:
[...]
tty:port1:mapped:38400 1STOPBIT 8DATABITS NONE -RXFAST -RXPROBE:RS232:NONE: :
vir4000:raw:0,0,0,0,40:port1:38400 1STOPBIT 8DATABITS NONE -RXFAST -RXPROBE -R
```

Buffer Overflow (CVE-2018-8865)



Conclusion

Responsible Disclosure

- All vulnerabilities have been sent to ICS-CERT
- They contacted the companies
- $\cdot\,$ After \pm 3 months \rightarrow public advisory

ICS-CERT NOUSTINAL CONTROL DYSTEMS CYTERE MERRORICY RESPONSE TEAM							٩		
номе	ABOUT	ICSJWG	INFORMATION PRODUCTS	TRAINING	FAQ				
Control Systems			Advisory (ICSA-17-320-01) More Advisories More Advisories More Advisories More Advisories						
Calendar			Print STweet 11:	Send Shar					
CSJWG			Legal Notice						
nformation Products			All information products included in http://cs-cert.us-cert.gov are provided "as is" for informational purposes only. The Department of Homeland Security (DHS) does not provide any warranties of any kind regularing any information contained within DHS does not endorse any commercial product or service, referenced in this product or donerwise.						
raining									
tecomme	nded Practic	es	information about TLP, see h	ttp://www.us-ce	t.gov/tlp/.				
ssessm	ints								
itandards & References		25	CVSS v3 8.6						
telated Sites			ATTENTION: Remotely exploitable/low skill level to exploit.						
ΆQ			Vendor: Moxa Equipment: NPort 5110, 5130, 5150						
			Vulnerabilities: Injection, In	formation Expo	ure Reso	urse Exhaustice			

Moxa

Example (Solved in firmware 2.8)

- SYN Flooding (CVE-2017-14028)
- Etherleaking (CVE-2017-16715)
- TCP ISN Prediction (CVE-2017-16715)
Example (Solved in firmware 2.8)

- SYN Flooding (CVE-2017-14028)
- Etherleaking (CVE-2017-16715)
- TCP ISN Prediction (CVE-2017-16715)

Still vulnerable

- Firmware Verification
- Connection blocking

Hi-Fly



Example (Solved)

Hi-Fly

Example (Solved)

Still vulnerable (No Answer)

- Open WLAN
- Connection blocking
- Small TCP window size

Lantech



Example (Solved)

Lantech

Example (Solved)

Still Vulnerable

- XSS (CVE-2018-8869)
- Buffer Overflow (CVE-2018-8865)

Lantech



Conclusion

- Found several severe security vulnerabilities on industrial serial device servers
- Often used in critical infrastructure
- If you use them, take extra care to protect these devices

Questions?

florian-hacklu@adamsky.it
https://florian.adamsky.it
Twitter: @c1t